









Date	Event
1-Jan-1993	In-study
1-Aug-2009	Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints
1-Jun-2013	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Apr-2018	Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study
1-Aug-2009	Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints
1-Mar-2015	Partial depth patching of PCC pavements at joints
1-Feb-2016	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study
1-Jul-2007	Partial depth patching of PCC pavements at joints
1-Jul-2010	Partial Depth Patching of PCC Pavement Other Than at Joint









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study
1-Jul-2007	Partial depth patching of PCC pavements at joints
1-Aug-2009	Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints
1-Aug-2011	Partial Depth Patching of PCC Pavement Other Than at Joint









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study
1-Aug-2009	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Jan-2013	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study
1-Jan-2013	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study
1-Jan-2013	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study
1-Nov-2007	Grinding Surface









Date	Event
1-Jan-1993	In-study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
12-Dec-2002	Crack Sealing
15-Nov-2003	Partial Depth Patching of PCC Pavement Other Than at Joint
15-Oct-2006	Partial Depth Patching of PCC Pavement Other Than at Joint
15-Nov-2008	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
12-Dec-2002	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
3-Dec-2002	Crack Sealing; Partial depth patching of PCC pavements at joints
15-Jun-2006	Partial depth patching of PCC pavements at joints
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
3-Dec-2002	Crack Sealing; Transverse Joint Sealing
15-Jun-2006	Partial depth patching of PCC pavements at joints
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
3-Dec-2002	Transverse Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
12-Dec-2002	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-Sep-1993	In-study
15-Jun-1996	Partial depth patching of PCC pavements at joints
5-Feb-1997	Lane-Shoulder Longitudinal Joint Sealing
15-Jun-2001	Partial depth patching of PCC pavements at joints
3-Dec-2002	Transverse Joint Sealing
20-Aug-2013	Out-of-Study









Date	Event
1-May-1999	In-study
1-Sep-2001	Lane-Shoulder Longitudinal Joint Sealing
1-May-2007	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Sep-2012	Partial Depth Patching of PCC Pavement Other Than at Joint
30-Jun-2017	Out-of-Study









Date	Event
1-May-1999	In-study
1-Sep-2004	Lane-Shoulder Longitudinal Joint Sealing
19-Nov-2015	Crack Sealing; Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing









Date	Event
1-May-1999	In-study
1-Sep-2001	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Sep-2004	Grinding Surface
1-Sep-2007	Grinding Surface









Date	Event
1-May-1999	In-study
1-Sep-2004	Lane-Shoulder Longitudinal Joint Sealing
1-May-2007	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
30-Jun-2017	Out-of-Study









Date	Event
1-May-1999	In-study
1-Sep-2001	Lane-Shoulder Longitudinal Joint Sealing
1-Sep-2013	Partial Depth Patching of PCC Pavement Other Than at Joint









Date	Event
1-May-1999	In-study
1-May-2007	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
19-Nov-2015	Crack Sealing; Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing









Date	Event
1-May-1999	In-study
1-May-2007	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
19-Nov-2015	Crack Sealing; Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing









Date	Event
1-May-1999	In-study
1-Sep-2001	Lane-Shoulder Longitudinal Joint Sealing
1-Sep-2004	Lane-Shoulder Longitudinal Joint Sealing
1-May-2007	Lane-Shoulder Longitudinal Joint Sealing









Date	Event
1-May-1999	In-study
1-Sep-2001	Lane-Shoulder Longitudinal Joint Sealing
1-Sep-2012	Partial depth patching of PCC pavements at joints
1-Sep-2017	Partial depth patching of PCC pavements at joints









Date	Event
1-May-1999	In-study
1-Sep-2004	Lane-Shoulder Longitudinal Joint Sealing
1-May-2007	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
19-Nov-2015	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing









Date	Event
1-May-1999	In-study
1-Sep-2001	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing









Date	Event
1-May-1999	In-study
1-Sep-2004	Lane-Shoulder Longitudinal Joint Sealing









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study
1-Jun-2004	Partial depth patching of PCC pavements at joints
1-Jun-2006	Partial depth patching of PCC pavements at joints
1-Jul-2011	Partial depth patching of PCC pavements at joints
30-Jun-2017	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Jun-2005	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Jul-2010	Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints
1-Sep-2016	Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study
1-Jul-2008	Partial depth patching of PCC pavements at joints
1-Jul-2010	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Jul-2011	Partial depth patching of PCC pavements at joints
26-Sep-2014	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Jun-2005	Partial depth patching of PCC pavements at joints
1-Jun-2008	Partial depth patching of PCC pavements at joints
1-Jun-2014	Partial depth patching of PCC pavements at joints
1-Jun-2015	Partial depth patching of PCC pavements at joints
1-Sep-2016	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study
1-Sep-2016	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study
1-Jul-2012	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study
30-Jun-2017	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Jun-1999	Partial depth patching of PCC pavements at joints
1-Jul-2003	Partial depth patching of PCC pavements at joints
1-Jun-2005	Partial depth patching of PCC pavements at joints
1-Jul-2012	Partial depth patching of PCC pavements at joints
1-Sep-2016	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study
1-Jul-2003	Partial depth patching of PCC pavements at joints
1-Jul-2014	Partial depth patching of PCC pavements at joints
1-Sep-2016	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1993	In-study
1-Jul-2012	Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1992	In-study
19-Apr-1996	Full Depth Transverse Joint Repair Patch
1-Jun-2000	Grinding Surface
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Jun-2000	Grinding Surface
1-Jun-2011	Partial depth patching of PCC pavements at joints
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
18-Apr-1996	Full Depth Transverse Joint Repair Patch; PCC Slab Replacement
1-Jun-2000	Grinding Surface
1-Jun-2007	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Mar-2012	Full Depth Transverse Joint Repair Patch
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Jun-2006	Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2008	Crack Sealing; Other
1-Mar-2011	Crack Sealing; Partial Depth Patching of PCC Pavement Other Than at Joint; Patch Pot Holes - Hand Spread, Compacted with Truck
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Jun-2000	Grinding Surface
1-Jun-2006	Lane-Shoulder Longitudinal Joint Sealing
1-Mar-2011	Patch Pot Holes - Hand Spread, Compacted with Truck
1-May-2012	Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
19-Apr-1996	Full Depth Transverse Joint Repair Patch
1-Jun-2000	Grinding Surface
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-May-1996	Full Depth Transverse Joint Repair Patch
1-Jun-2000	Grinding Surface
1-Jun-2002	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Jun-2006	Lane-Shoulder Longitudinal Joint Sealing
1-Mar-2011	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Jun-2000	Grinding Surface
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Jun-2000	Grinding Surface
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1992	In-study
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Apr-2016	Out-of-Study









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration
1-Jan-2019	Patch Pot Holes - Hand Spread, Compacted with Truck









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Crack Sealing









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)









Date	Event
1-Jan-1994	In-study
1-Jun-2005	PCC Slab Replacement
1-Jun-2006	Full Depth Patching of PCC Pavement Other Than at Joint; Lane-Shoulder Longitudinal Joint Sealing; PCC Slab Replacement; Transverse Joint Sealing
1-Jun-2013	AC Shoulder Restoration; PCC Slab Replacement; Partial depth patching of PCC pavements at joints
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Jan-2019	Patch Pot Holes - Hand Spread, Compacted with Truck









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Jan-2019	PCC Slab Replacement









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Partial depth patching of PCC pavements at joints
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Partial depth patching of PCC pavements at joints
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints
1-Jun-2014	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration









Date	Event
1-Jan-1992	In-study
5-Dec-1995	PCC Slab Replacement; Partial depth patching of PCC pavements at joints
1-Jun-2002	PCC Slab Replacement
9-Sep-2004	PCC Slab Replacement
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2011	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch
1-Jun-2015	Grinding Surface
1-Jan-2019	Patch Pot Holes - Hand Spread, Compacted with Truck









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2011	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing









Date	Event
1-Jan-1992	In-study
1-Jun-1995	Partial depth patching of PCC pavements at joints
1-Apr-1997	Partial depth patching of PCC pavements at joints
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2011	Full Depth Transverse Joint Repair Patch









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2008	Partial depth patching of PCC pavements at joints
1-Jun-2010	Partial depth patching of PCC pavements at joints
1-Jun-2011	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch
1-Jun-2014	Partial depth patching of PCC pavements at joints
1-Jan-2019	Patch Pot Holes - Hand Spread, Compacted with Truck









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2011	PCC Slab Replacement









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2008	Partial depth patching of PCC pavements at joints
1-Jun-2011	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2011	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2011	Full Depth Transverse Joint Repair Patch
1-Jan-2019	Patch Pot Holes - Hand Spread, Compacted with Truck









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2011	Full Depth Transverse Joint Repair Patch









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing









Date	Event
1-Jan-1992	In-study
22-Apr-2005	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jun-2011	Full Depth Patching of PCC Pavement Other Than at Joint









Date	Event
1-Jan-1993	In-study
1-Sep-1999	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Jun-2002	Lane-Shoulder Longitudinal Joint Sealing; PCC Slab Replacement
14-Oct-2003	AC Shoulder Restoration; Full Depth Transverse Joint Repair Patch; Partial depth patching of PCC pavements at joints
20-Oct-2003	Out-of-Study









Date	Event
1-Jan-1993	In-study
2-May-2000	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Nov-2002	Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2008	Partial depth patching of PCC pavements at joints
1-Jan-2013	Out-of-Study









Date	Event
1-Jan-1993	In-study
17-Aug-1999	Out-of-Study









Date	Event
1-Jan-1993	In-study
20-Sep-1998	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Nov-2002	AC Shoulder Restoration
1-Sep-2003	Partial depth patching of PCC pavements at joints
1-Jun-2006	Partial depth patching of PCC pavements at joints
1-Jun-2010	AC Shoulder Restoration
1-Jan-2013	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Nov-2002	Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2008	Partial depth patching of PCC pavements at joints
1-Jan-2013	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Nov-2002	Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2008	Partial depth patching of PCC pavements at joints
1-Jan-2013	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Nov-2002	Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2007	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Nov-2002	Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2008	Partial depth patching of PCC pavements at joints
1-Jan-2013	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Nov-2002	Lane-Shoulder Longitudinal Joint Sealing
1-Jan-2013	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Apr-2000	Lane-Shoulder Longitudinal Joint Sealing; Transverse Joint Sealing
1-Jan-2013	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-May-1997	Full Depth Patching of PCC Pavement Other Than at Joint
15-Sep-1997	Crack Sealing
4-Oct-1999	Full Depth Patching of PCC Pavement Other Than at Joint
3-May-2000	Full Depth Patching of PCC Pavement Other Than at Joint
1-Jun-2003	Full Depth Patching of PCC Pavement Other Than at Joint
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-May-1997	Crack Sealing; Partial Depth Patching of PCC Pavement Other Than at Joint
18-Sep-1997	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Oct-1995	Crack Sealing
15-Sep-1997	Crack Sealing
1-May-2000	Partial depth patching of PCC pavements at joints
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Oct-1995	Partial Depth Patching of PCC Pavement Other Than at Joint
1-May-1996	Partial Depth Patching of PCC Pavement Other Than at Joint
1-May-1997	Crack Sealing; Partial depth patching of PCC pavements at joints
15-Sep-1997	Crack Sealing
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Oct-1995	Crack Sealing
15-Sep-1997	Crack Sealing
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-May-1997	Partial Depth Patching of PCC Pavement Other Than at Joint
18-Sep-1997	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-May-1997	Partial depth patching of PCC pavements at joints
15-Sep-1997	Crack Sealing
1-May-2000	Partial depth patching of PCC pavements at joints
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Oct-1995	Partial Depth Patching of PCC Pavement Other Than at Joint
15-Sep-1997	Crack Sealing
1-May-2002	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
15-Sep-1997	Crack Sealing
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Oct-1995	Crack Sealing
15-Sep-1997	Crack Sealing
1-Jan-2004	Out-of-Study









Date	Event
1-Jan-1993	In-study
1-Jan-2004	Out-of-Study









Date	Event
15-Jul-1992	In-study
31-Dec-2003	Out-of-Study









Date	Event
15-Jul-1992	In-study
31-Dec-2003	Out-of-study









Date	Event
15-Jul-1992	In-study









Date	Event
15-Jul-1992	In-study









Date	Event
15-Jul-1992	In-study
31-Dec-2003	Out-of-Study









Date	Event
15-Jul-1992	In-study
31-Dec-2003	Out-of-Study









Date	Event
15-Jul-1992	In-study









Date	Event
15-Jul-1992	In-study









Date	Event
15-Jul-1992	In-study
31-Dec-2003	Out-of-Study









Date	Event
15-Jul-1992	In-study
1-Jun-1995	Partial depth patching of PCC pavements at joints
31-Dec-2003	Out-of-Study









Date	Event
15-Jul-1992	In-study









Date	Event
15-Jul-1992	In-study
1-Jun-2015	Patch Pot Holes - Hand Spread, Compacted with Truck









Date	Event
15-Jul-1992	In-study
1-Jun-1995	Partial depth patching of PCC pavements at joints









Date	Event
15-Jul-1992	In-study









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints; Transverse Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2005	AC Shoulder Restoration
1-Jun-2006	Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints; Transverse Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration; Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2005	AC Shoulder Restoration
1-Jun-2006	Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints; Transverse Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2015	Skin Patching (hand tools/hot pot to apply liquid asphalt and aggregate)
1-Jun-2016	AC Shoulder Restoration; Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
31-Aug-1999	Partial depth patching of PCC pavements at joints
1-Sep-2000	Partial depth patching of PCC pavements at joints
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints; Transverse Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
30-Jun-1998	Crack Sealing; Partial depth patching of PCC pavements at joints
31-Aug-1999	Partial depth patching of PCC pavements at joints
1-Aug-2001	Crack Sealing; Lane-Shoulder Longitudinal Joint Sealing
1-Sep-2001	AC Shoulder Restoration
1-Aug-2002	Crack Sealing; Lane-Shoulder Longitudinal Joint Sealing
1-Aug-2005	AC Shoulder Restoration; Crack Sealing; Lane-Shoulder Longitudinal Joint Sealing; Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints
30-Sep-2009	AC Shoulder Restoration; Crack Sealing; Full Depth Transverse Joint Repair Patch; Lane-Shoulder Longitudinal Joint Sealing; PCC Slab Replacement; Partial depth patching of PCC pavements at joints; Transverse Joint Sealing









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints; Transverse Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2014	Patch Pot Holes - Hand Spread, Compacted with Truck
1-Jun-2016	AC Shoulder Restoration; Full Depth Transverse Joint Repair Patch; Saw and Seal









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration; Full Depth Patching of PCC Pavement Other Than at Joint









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration; Full Depth Transverse Joint Repair Patch









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration; Full Depth Transverse Joint Repair Patch









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints; Transverse Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration; Full Depth Transverse Joint Repair Patch; Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2014	Patch Pot Holes - Hand Spread, Compacted with Truck
1-Jun-2016	AC Shoulder Restoration; Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1994	In-study
30-Sep-2009	Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints; Transverse Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2016	Partial Depth Patching of PCC Pavement Other Than at Joint; Partial depth patching of PCC pavements at joints









Date	Event
1-Jan-1994	In-study
30-Sep-2009	Lane-Shoulder Longitudinal Joint Sealing; Partial depth patching of PCC pavements at joints
1-May-2011	Grinding Surface









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2014	Patch Pot Holes - Hand Spread, Compacted with Truck
1-Jun-2016	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
1-Sep-2001	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-Jun-2006	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
30-Sep-2009	AC Shoulder Restoration; Lane-Shoulder Longitudinal Joint Sealing
1-May-2011	Grinding Surface
1-Jun-2014	Patch Pot Holes - Hand Spread, Compacted with Truck
1-Jun-2016	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
17-Jul-1997	AC Shoulder Restoration
19-Aug-2009	AC Shoulder Restoration
1-May-2011	Grinding Surface
1-Jun-2016	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
1-May-2011	Grinding Surface









Date	Event
1-Jan-1994	In-study
16-Feb-2007	Out-of-Study









Date	Event
1-Jan-1994	In-study
16-Feb-2007	Out-of-Study









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Grinding Surface
1-Jan-2019	PCC Slab Replacement









Date	Event
1-Jan-1994	In-study
16-Feb-2007	Out-of-Study









Date	Event
1-Jan-1994	In-study
16-Feb-2007	Out-of-Study









Date	Event
1-Jan-1994	In-study
16-Feb-2007	Out-of-Study









Date	Event
1-Jan-1994	In-study
13-Aug-2012	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch; Joint Load Transfer Restoration in PCC Pavements
1-Jun-2013	AC Shoulder Restoration; Other; PCC Slab Replacement
1-Jan-2019	PCC Slab Replacement









Date	Event
1-Jan-1994	In-study
20-Jun-2007	Full Depth Transverse Joint Repair Patch; Joint Load Transfer Restoration in PCC Pavements
13-Aug-2012	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch; Joint Load Transfer Restoration in PCC Pavements
1-Jun-2013	AC Shoulder Restoration; Full Depth Patching of PCC Pavement Other Than at Joint; Other; PCC Slab Replacement
1-Jan-2019	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch; PCC Slab Replacement
1-Jan-2020	Out-of-Study









Date	Event
1-Jan-1994	In-study
20-Jun-2007	Full Depth Transverse Joint Repair Patch; Other
1-Sep-2012	Out-of-Study









Date	Event
1-Jan-1994	In-study
16-Feb-2007	Out-of-Study









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration









Date	Event
1-Jan-1994	In-study
20-Jun-2007	Full Depth Transverse Joint Repair Patch; Joint Load Transfer Restoration in PCC Pavements
1-Jun-2010	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Jun-2012	Partial Depth Patching of PCC Pavement Other Than at Joint
13-Aug-2012	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch; Joint Load Transfer Restoration in PCC Pavements
1-Jun-2013	AC Shoulder Restoration; Other; PCC Slab Replacement
1-Jun-2015	Patch Pot Holes - Hand Spread, Compacted with Truck
1-Jan-2019	Full Depth Patching of PCC Pavement Other Than at Joint; Full Depth Transverse Joint Repair Patch; PCC Slab Replacement
1-Jan-2020	Out-of-Study









Date	Event
1-Jan-1994	In-study
16-Feb-2007	Out-of-Study









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration
1-Jan-2019	PCC Slab Replacement









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Grinding Surface









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Grinding Surface









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration; Grinding Surface









Date	Event
1-Jan-1994	In-study
20-Jun-2007	Full Depth Transverse Joint Repair Patch; Other
1-Sep-2012	Out-of-Study









Date	Event
1-Jan-1994	In-study
1-Jun-2013	AC Shoulder Restoration









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study
1-Jul-2011	Partial depth patching of PCC pavements at joints
1-Jun-2015	Partial Depth Patching of PCC Pavement Other Than at Joint
1-Mar-2017	Partial Depth Patching of PCC Pavement Other Than at Joint
5-Jun-2017	Partial Depth Patching of PCC Pavement Other Than at Joint
3-Jun-2018	Partial Depth Patching of PCC Pavement Other Than at Joint









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1993	In-study









Date	Event
1-Jan-1997	In-study
1-Jun-2014	Patch Pot Holes - Hand Spread, Compacted with Truck









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study
1-Jun-2011	Patch Pot Holes - Hand Spread, Compacted with Truck









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study
14-Jun-2007	Grinding Surface









Date	Event
1-Jan-1997	In-study









Date	Event
1-Jan-1997	In-study
1-Jan-2019	Patch Pot Holes - Hand Spread, Compacted with Truck





Date	Event
1-Jan-1997	In-study
1-Jun-2000	PCC Slab Replacement





Date	Event
1-Jan-1997	In-study

